



Total Care Property Inspections
1582 Victoria Ave
Lakewood, OH 44107

Home Inspection Report



Somewhere
Cleveland, Ohio

Total Care Property Inspections

Sample Picture Report.alb5

10:16 July 16, 2009

Page 1 of 3



Curling and Cupping Shingles



Concrete in driveway needs repaired



Recommend painting



Paint peeling



Possible visible mold



Possible visible mold

Total Care Property Inspections

Sample Picture Report.alb5

10:16 July 16, 2009

Page 2 of 3



Knob and tube wiring




Paint Peeling



Paint Peeling



Possible Asbestos floor tiles




Total Care Property Inspections

Sample Picture Report.alb5

10:16 July 16, 2009

Page 3 of 3



Double tap in the electric panel



Knockout needs to be sealed




Trip Hazard



Trip hazard and downspout need to be resealed



Downspout rusting



Nails coming out of the gutters